



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrds.state.nm.us/ocd/District/III3district.htm>

MC 30-4-13 #11

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 8/17/2012 Operator Blackhills API #30-0 39-29869

Property Name MC30-04-13 Well No. 111 Location: Unit      Section 13 Township 30N Range 3E

Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate      Casing 31 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	0		71		
10 min	0		92		
15 min	0		106		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<input checked="" type="checkbox"/>	
Nothing	<input checked="" type="checkbox"/>	
Gas	<input checked="" type="checkbox"/>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

OIL CONS. DIV DIST. 3

SEP 18 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS: Good Pool when opened about 5 seconds  
down to nothing, small pool after 5 min shut in  
0 on Gauge

By Robert Talamante  
lease operator  
(Position)

Witness     

Oil Cons. Div  
District III

AUG 20 2012

E-mail address     

R ca