



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/District.htm](http://emrnr.state.nm.us/ocd/District%20III/District.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 02 2012

Date of Test 9-21-12 Operator Chevron API # 30-039 0707 0

Property Name Rincon Well No 161 Location: Unit Section 17 Township 27 Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 137 Intermediate N/A Casing 129 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>1</u>	<u>129</u>	<u>X</u>	<u>X</u>
10 min	<u>0</u>	<u>1</u>	<u>129</u>	<u>X</u>	<u>X</u>
15 min	<u>0</u>	<u>1</u>	<u>129</u>	<u>X</u>	<u>X</u>
20 min				<u>X</u>	<u>X</u>
25 min				<u>X</u>	<u>X</u>
30 min				<u>X</u>	<u>X</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

By Randy Culcote

Witness

Culder Service
(Position)

E-mail address Randy.C@calderservice.com