June 30, 2005

Koch Exploration Po Box 489 Aztec, NM 87410

30-045-32593

This letter is to certify that D&D Services LLC did run deviation surveys at the below listed depths on your Oxnard 334 S S8 T31N R8W in San Juan County, New Mexico.

285

1

To the best of my knowledge, I swear this information to be true.

Sincerely,

Glen Davis

Drilling Manager

WELLIE L. BARRETT NOTARY PUBLIC STATE OF NEW MEXICO

My Commission Expires:



MAILING ADDRESS: PO BOX 3483 FARMINGTON, NM 87499 SHIPPING ADDRESS: 3600 BLOOMFIELD HWY FARMINGTON, NM 87401 OFFICE: (505) 325-1125 FAX: (505) 326-4803

August 31, 2005

RE: Deviation Surveys

To Whom It May Concern:

The enclosed Daily Reports are true and accurate copies that were sent to Koch Production based on the paperwork we received from our operators.

Yours truly,

Phoenix Services, LLC Rony & Simson

Rony E. Simmons

Manager

Enclosures

Subscribed and sworn/affirmed before me this 31 at day of August

My Commission Expires:



Phoenix

Services, LLC

P.O. Box 3483 Farmington, NM 87499-3483

Office (505) 325-1125 Pager(505) 564-5453 DAILY REPORT

Date: AUGUTS 1, 2005

No. 5927WD

File No. Unit No. 5

Information from company file:

Tbg. Size: 3 1/2" Total Depth:

Perfs:

Company Name: KOCH PRODUCTION

Well Name: OXNARD 334S County, State: SAN JUAN, NM

Foreman: LESLIE LAM

Pumper: AFE or DP#:

> Casing Psi: Tubing Psi: Gauge Ring:

Total Depth: 785'

Fluid Level:

Tight Spots: Equipment Set @:

Piston Serial #:

Bumper Spring Serial #:

Description of work performed:

RAN DEVIATION TOOL TO 785'-SHOT- SHOWED 1 DEGREE-LEFT DISK W/ PUMPER-RELEASED FROM LOCATION







Phoenix

Services, LLC

P.O. Box 3483 Farmington, NM 87499-3483

Office (505) 325-1125 Pager (505) 564-5453

Company Name: KOCH Production Well Name: OXNARD 334S

County, State: SAN JUAN, NM

Foreman: DALTON KING

Pumper: AFE or DP#:

> Casing Psi: 0 **Tubing Psi:** Gauge Ring: Total Depth:

Fluid Level: SURFACE

Tight Spots: Equipment Set @: Piston Serial #:

Bumper Spring Serial #:

Description of work performed:

RAN DEVIATION TOOL TO 1285'-SHOT-SHOWED 1 DEGREE-RAN DEVIATION TOOL TO 1785'-SHOT-SHOWED 4 DEGREES-RAN DEVIATION TOOL TO 1785'-SHOT-SHOWED 5 DEGREES-RAN DEVIATION TOOL TO 2285'-SHOT-SHOWED 2 DEGREES-LEFT DISKS W/PUMPER-RELEASED FROM LOCATION

DAILY REPORT

Date: AUGUST 10, 2005

No. 5999W

File No. Unit No. 5

Information from company file:

Tbg. Size: Total Depth: Perfs:





Phoenix Services, LLC

DAILY REPORT

P.O. Box 3483

Farmington, NM 87499-3483

Office (505) 325-1125

Pager (505) 564-5453

Date: AUGUST 12 2005,

No. 6022WD

File No. 603

Unit No. 1

Company Name: KOCH PRODUCTION

Well Name: OXNARD 334S County, State: SAN JUAN, NM Information from company file:

Tbg. Size:

Total Depth:

Perfs:

Foreman: DALTON KING

Pumper: AFE or DP#:

Casing Psi:

Tubing Psi:

Gauge Ring:

Total Depth: 2621'

Fluid Level:

Tight Spots:

Equipment Set @:

Piston Serial #:

Bumper Spring Serial #:

Description of work performed:

RAN DEVATION TOOL TO 2621'-TD-PULLED UP TO 2606'-SHOT-SHOT SHOWED 3 DEGREES-LEFT DISK W/ PUMPER-RELEASED FROM LOCATION



FAXED

AUG 116 2005



Phoenix

Services, LLC

P.O. Box 3483 Farmington, NM 87499-3483 Date: AUGUST 13, 2005

DAILY REPORT

Office (505) 325-1125 Pager (505) 564-5453 No. 6030WD File No. 604 Unit No. 1

Company Name: KOCH PRODUCTIONS

Well Name: OXNARD 334S
County, State: SAN JUAN, NM

Information from company file:

Tbg. Size: Total Depth: Perfs:

Foreman: DALTON KING

Pumper: AFE or DP#:

Casing Psi: Tubing Psi: Gauge Ring:

Total Depth: 3057'

Fluid Level: Tight Spots: Equipment Set @: Piston Serial #:

Bumper Spring Serial #:

Description of work performed:

RAN DEVATION TOOL TO 3057'-TD-PULLED UP 3037'-SHOWED 1 DEGREE-RELEASED FROM LOCATION





FAXED

AUG 16 2005