



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3distric.htm](http://emrdr.state.nm.us/ocd/District%20III/3distric.htm)

RCVD MAR 4 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3/6/2013 Operator Buckington API #30-0 4587-26849
Property Name Huefano Unit Well No. 287 Location: Unit C Section 5 Township 26 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 2 Intermediate NA Casing 10.5 Bradenhead 3.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		555		
10 min	0		615		
15 min	0		610		
20 min	0		610		
25 min	0		608		
30 min	0		605		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Blew down to nothing in 10 sec. BHT ran w/ MIT, casing pressured up to 620psi. BH through 1/4" valve.

By Fred Gorrion COPC
Specialist
(Position)

Witness

Jonette D. Kelly

E-mail address _____