



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6179
<http://omard.state.nm.us/ocd/District11/District11.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-5-13 Operator Kevin midant API #30-0 39-07009

Property Name Rincon Well No. 116 Location: Unit D Section 21 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 21 Intermediate X Casing 49 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	49		
10 min	0	1	49		
15 min	0	1	49		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE X

REMARKS:

By Randy calder

calder services

(Position)

Witness _____ OIL CONS. DIV DIST. 3

MAR 08 2013

E-mail address Randy.c@calderservices.com

3-6-13