

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 27 2013

Date of Test: 3-21-13 Operator: CHevron medical TAPI #30-039-20157

Property Name Rincon Well No. 146 Location: Unit 6 Section 23 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate X Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	79		
10 min	0	1	79		
15 min	0	1	79		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing X	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6 INTERMEDIATE X

REMARKS:

By Randy caldwell
caldwell services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-25-1