



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1800 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 324-6170
<http://sm.nrd.state.nm.us/ocd/District1123/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 22 2013

Date of Test 3-18-13 Operator Cherna incident API #30-0 39-27814

Property Name Rincon Well No. 403 Location: Unit P Section 21 Township 27 Range 6

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 31 Intermediate 0 Casing 57 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	56	0	57
10 min	0	0	55	0	56
15 min	0	0	57	0	56
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

By Randy calcote
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-20-13