



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emr.state.nm.us/ocd/District III/3district.htm](http://emr.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 10 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-10-2013 Operator BULLINGTON API #30-0 39-23465
Property Name LWORTH 13 Well No. 24 Location: Unit 7 Section 7 Township 24 Range 3
Well Status(Shut-In or Producing) Initial PSI: Tubing 71 Intermediate 0 Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	1	0	70	1	71
10 min	1	0	70	1	71
15 min	1	0	70	1	71
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing		X	X
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADEN HEAD NOTHING
CAME OUT OPENED THE INTER MEDIANE NOTHING CAME OUT

By Bud Dwyer

Witness John Dwyer

(Position)

E-mail address _____