



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD APR 10 '13

OIL CONS. DIV.

DIST. 3

Date of Test 10-APR-2013 Operator BURLINGTON API #30-0 39-23609

Property Name LINDRITH 13 UNIT Well No. 27 Location: Unit M Section 10 Township 24 Range 3

Well Status(Shut-In or Producing) Initial PSI: Tubing 63 Intermediate 0 Casing 63 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int.	Csg	Int	Csg
TIME					
5 min		0	63		64
10 min		0	63		64
15 min		0	63		64
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADEN HEAD NOTHING CAME OUT.
OPENED THE INTERMEDIATE NOTHING CAME OUT

By Burlington

Witness John Durham

(Position)

E-mail address _____