

NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

RCVD APR 3 '13

OIL CONS. DIV.

DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-3-13 Operator Chusza Oil Co. API # 30-0 45-09696

Property Name NE Hogback Mt. Well # 31 Location: Unit K Sec 10 Twn 30 Rge 16

Land Type:

State _____
Federal /
Private _____
Indian _____

Well Type:

Water Injection /
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N

TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 190
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 700 psi. for 30 mins. Test passed failed

REMARKS:

Pressure set at 1528
for perf 1596-1628

By


[Signature]
(Operator Representative)

Witness

[Signature]
(NMOCD)

PRESIDENT
(Position)

Revised 02-11-02



Graphic Controls
30.0K-09696
CHART NO. MC MP-1000-IHR
well check of Farmington
METER _____
CHART PUT ON _____ M TAKEN OFF _____ M
LOCATION 164 Haystack #31
REMARKS 10-30-16
4-3-13 J. J. J.
Pass MIT inspection

[Handwritten signature]
10-30-16