



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD APR 24 '13
OIL CONS. DIV.
DIST. 3

Date of Test 4/24/2013 Operator Burlington API #30-0 31-06795
Property Name Harrington Well No. 1 Location: Unit M Section 31 Township 27 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate 5 Casing 29 Bradenhead 4.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	30	0	32
10 min	0	0	31	0	33
15 min	0	0	31	0	33
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH blew down in 30 sec through 1/4" fitting, Intermediate bleed down to nothing through threads of fitting while starting test.

By [Signature]

Witness [Signature]

MSO
(Position)

E-mail address _____