

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: State Com J 6 Pipeline C4	Facility Type: Pipeline

Surface Owner State	Mineral Owner State (B-10938)	API No. 30-045-10070
----------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	36	31N	9W	1650	South	990	West	San Juan

Latitude **36.851951** Longitude **107.73759**

RCUD MAR 21 '13
OIL CONS. DIV.
DIST. 3

NATURE OF RELEASE

Type of Release Produced Water & Hydrocarbon	Volume of Release 1bbl	Volume Recovered None
Source of Release Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 3/15/2013 at 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell (NMOCD)	
By Whom? Crystal Tafoya	Date and Hour 3/15/2013 at 3:30pm	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 1 bbls	

If a Watercourse was Impacted, Describe Fully.*

Pipeline leak was discovered in the middle of a natural drainage. The spill was contained to a 5' diameter with a depth of approximately 2". The site was bermed to prevent traveling. No surface water was impacted.

Describe Cause of Problem and Remedial Action Taken.*

The SJ C4 gas pipeline developed a leak which released produced water and condensate at a point where the line crosses a small wash. The wells on the pipeline were immediately shut-in and the spill site bermed.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Crystal Tafoya	Approval Date: 4/25/2013	Expiration Date:
Title: Field Environmental Specialist	Conditions of Approval:	
E-mail Address: crystal.tafoya@conocophillips.com	Attached <input type="checkbox"/>	
Date: 3/20/2013 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

WJK1311548006