NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

OIL CONS. DIV DIST. 3

MAR 27 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-22-13 Operator Chevron Incident API #30-0 39-27009

Property Name Rincon Well No. 182R Location: Unit B Section 26 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 110 Intermediate 1 Casing 110 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME					
5 min	0	1	110	0	110
10 min	0	1	110	0	110
15 min	0	1	110	0	110
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	3 sec	
Nothing		X Puff
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Randy Alcote Witness

Calder services
(Position)

E-mail address Randy.c@calderservices.com

3-26-13