



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8778 FAX: (505) 334-6170
<http://amrd.state.nm.us/ocd/DistrictIDistrict.htm>

OIL CONS. DIV DIST. 3

MAR 22 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-15-13 Operator Chevron midcon TAPI #30-039-27525

Property Name Rizon Well No. 126a Location: Unit J Section 27 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate 21 Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	0	75	0	75	
10 min	0	0	75	0	75	
15 min	0	0	75	0	75	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing X

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1

REMARKS:

By Randy calder
calder services
(Position)

Witness

E-mail address Randy.c@calder-services.com

3-20-13