



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

RCVD MAY 13 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-13-13 Operator Burlington API #30-0 45-30511
Property Name Al:8mLH Well No. 38B Location: Unit 17 Section 17 Township 32 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 156 Intermediate N/A Casing 155 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		155		
10 min	0		156		
15 min	0		156		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	
Nothing		
Gas	/	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS

BH Puff when opened.

Broken tools in tubing

By Raymond Belcham

Witness Monica Keckling

MSO
(Position)

E-mail address _____