



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

RCVD MAY 17 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 5/17/13 Operator McElvan Energy API # 30-0 45-35043

Property Name Big Gap SW Well No. 1 Location: Unit Section 20 Township 30 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 980 Intermediate 1/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE 1/A

REMARKS:

BH- nothing when opened.

By

(Position)

Witness

E-mail address