



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 6 '13

OIL CONS. DIV.

DIST. 3

Date of Test 6-JUNE-2013 Operator QUINCO API #30-0 39-26278

Property Name SAN JUAN 27-4 Well No. 98B Location: Unit L Section 10 Township 27 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 157 Intermediate N/A Casing 158 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>5</u>	<u>N/A</u>	<u>158</u>		
10 min	<u>5</u>	<u>N/A</u>	<u>158</u>		
15 min	<u>5</u>	<u>N/A</u>	<u>158</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: OPENED THE BRADENHEAD AND NOTHING
CAME OUT

By Cory Schulte

Witness [Signature]

(Position)

E-mail address _____