



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

RCVD JUN 6 '13

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6 - JUNE - 2013 Operator CONOCO API #30-0 39-30484

Property Name SAN JUAN 27-4 Well No. 140C Location: Unit 1 Section 10 Township 27 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 180 Intermediate 0 Casing 180 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u> </u>	<u>0</u>	<u>185</u>	<u> </u>	<u>186</u>
10 min	<u> </u>	<u>0</u>	<u>185</u>	<u> </u>	<u>185</u>
15 min	<u> </u>	<u>0</u>	<u>185</u>	<u> </u>	<u>185</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>X</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT.

By Cory Schultz

Witness John Adams

(Position)

E-mail address