

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Blanco 2S Transfer Station	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004531897
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter J	Section 05	Township 31N	Range 08W	Feet from the 1760	North/South Line South	Feet from the 1330	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.92385 Longitude 107.69377

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 50.32 bbls	Volume Recovered: none
Source of Release: 1/4 inch nipple on discharge piping	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: 6/1/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD	
By Whom? Courtney Cochran - BP	Date and Hour: 6/3/2013 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD JUN 5 '13
OIL CONS. DIV.
DIST. 3


Describe Cause of Problem and Remedial Action Taken.*

Field technician arrived on location and found the 1/4 inch nipple broken on the discharge piping of the pump. Nipple was repaired and unit returned to service. Spill raked in place.

Describe Area Affected and Cleanup Action Taken.*

Spill was contained in secondary containment and did not leave location. No produced water was recovered due to the fact that it was completely absorbed by the ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: 6/11/2013	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/03/2013 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

25K1316228048