



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 18 '13

OIL CONS. DIV.

DIST. 3

Date of Test 18-JUNE-2013 Operator CONOCO API #30-0 39-20466

Property Name SAN JUAN 27-5 Well No. 142 Location: Unit B Section 33 Township 27 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 177 Intermediate 0 Casing 176 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>0</u>	<u>176</u>	<u>1</u>	<u>176</u>
10 min	<u>1</u>	<u>0</u>	<u>176</u>	<u>1</u>	<u>176</u>
15 min	<u>1</u>	<u>0</u>	<u>176</u>	<u>1</u>	<u>176</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN IN LESS
THAN 1 SECOND

By [Signature]

Witness [Signature]

(Position)

E-mail address _____