



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 18 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-18-2013 Operator COPC API #30-0 39-20840

Property Name San Juan 28-6 Well No. 104 Location: Unit 1C Section 8 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 125 Intermediate 29 Casing 129 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	29	131	0	134
10 min	0	29	132	0	135
15 min	0	29	133	0	136
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0.2

REMARKS:

Nothing on bradenhead. Intermediate blew down to
fumes in 33 seconds.

By [Signature]
(Position) MSU

Witness Paul Wrede

E-mail address _____