



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 14 '13
OIL CONS. DIV.
DIST. 3

Date of Test 6-14-2013 Operator COPC API #30-039-26959

Property Name Son Juan 28-7 Well No. 2276 Location: Unit Section 36 Township 28 Range 7

Well Status(~~Shut-In~~ or Producing) Initial PSI: Tubing 83 Intermediate 304 Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	304	87	0	89
10 min	0	304	88	0	90
15 min	0	304	89	0	90
20 min				0	90
25 min				0	91
30 min				0	91

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		vapor
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0.2

REMARKS:

Nothing on bradenhead. Intermediate, hard blow for
4 minutes 50 seconds, down to just vapor for rest of test.

By [Signature]
M50
(Position)

Witness Paul Wake

E-mail address