



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-1-2013 Operator COPC API #30-0 39-25474

Property Name San Juan Well No. 99M Location: Unit F Section 24 Township 28 Range 6

Well Status(~~Shut-In~~ or Producing) Initial PSI: Tubing 173 Intermediate — Casing 178 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>178</u>		
10 min	<u>0</u>	<u>—</u>	<u>178</u>		
15 min	<u>0</u>	<u>—</u>	<u>178</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

JUL 01 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS: Nothing on bradenhead

By [Signature]
msd
(Position)

Witness Paul Wiche

E-mail address —