



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-1-2013 Operator COPC API #30-0 39-30948

Property Name San Juan 28-6 Well No. 4335 Location: Unit D Section 24 Township 28 Range 6

Well Status(~~Shut In~~ or Producing) Initial PSI: Tubing 151 Intermediate - Casing 152.6 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	-	158		
10 min	0	-	158		
15 min	0	-	158		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
JUL 01 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead, hard puff (1 second)

By [Signature]
MSD
(Position)

Witness Paul Wiche

E-mail address _____