



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD JUN 27 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.
DIST. 3

Date of Test 27-JUNE-2013 Operator CONOCO API #30-0 39-26970

Property Name SAN JUAN 28-7 Well No. 1948 Location: Unit 0 Section 21 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 110 Intermediate 16 Casing 15 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	/	16	120	/	124
10 min	/	16	121	/	124
15 min	/	16	122	/	125
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	X		X
Nothing			
Gas	X		X
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE 2

REMARKS: OPENED THE BRADENHEAD AND IT BLEW DOWN NOTHING
IN LESS THAN 1 SECOND, OPENED THE INTERMEDIATE
AND IT BLEW DOWN IN 1:25 MINUTES

By JUAN CARDENAS
Area 23 MSO

Witness JOSE MORALES

(Position)

E-mail address _____