



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

RCVD JUL 10 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 7/10/2013 Operator ConocoPhillips API #30-0 39-07258

Property Name San Juan 28-7 Unit Well No. 69 Location: Unit 6 Section 32 Township 28 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 136 Intermediate NA Casing 138 Bradenhead 4.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		139		
10 min	0		139		
15 min	0		140		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	X		
Nothing			
Gas	X		
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Through 1" fitting. BH blew down in 15 sec.

By Jennifer D. Beardsley

(Position)

Witness Jonathan D. Kelly

E-mail address _____