



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

RCVD JUL 10 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/10/2013 Operator ConocoPhillips API #30-0 39-30671
Property Name San Juan 287 well Well No. 251M Location: Unit 0 Section 31 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 221 Intermediate 283 Casing 243 Bradenhead -1.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	283	247	0.1	246
10 min	0	283	248	0.1	242
15 min	0	283	248	0.1	240
20 min				0.1	239
25 min				0	238
30 min				0	238

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X X
Nothing		
Gas		X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0.2

REMARKS:

BH had slight vacuum to nothing in 3 sec, through 1" fittings, Intermediate blew hard through 1" for 4 min, down to ^{almost} nothing in 6 min, well flowing through Intermediates. down to nothing in 25 min. Slight pressure on 5 min shut.

By

Jennifer L. Bidsley

(Position)

Witness

Jonathan D. Kelly

E-mail address _____