



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUL 16 2013

Date of Test 7-16-2013 Operator COPC API #30-0 39-22229

Property Name San Juan 28-5 Well No. 29A Location: Unit D Section 18 Township 28 Range 5

Well Status(~~Shut In~~ or Producing) Initial PSI: Tubing 149 Intermediate — Casing 152 Bradenhead -1.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>152</u>		
10 min	<u>0</u>	<u>—</u>	<u>153</u>		
15 min	<u>0</u>	<u>—</u>	<u>153</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

very slight suction on bradenhead

By [Signature]

Witness Paul Wicks

(Position)

E-mail address —