



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 19-JUL-2013 Operator CONOCO API #30-0 39-3603
Property Name SAN JUAN 28-6 Well No. 107N Location: Unit N Section 4 Township 27 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 96 Intermediate 125 Casing 109 Bradenhead 125

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		129	108		112
10 min		129	108		117
15 min		126	112		118
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			X
Nothing	X		
Gas			X
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD JUL 19 '13
OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND IT BLEW DOWN IN 1:35
MINUTES.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____