



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 23 '13
OIL CONS. DIV.
DIST. 3

Date of Test 23-JUL-2013 Operator CONOCO API #30-0 39-07097

Property Name SAN JUAN 28-6 Well No. 67 Location: Unit 4 Section 14 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 83 Intermediate 190 Casing 99 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	BH	Bradenhead		INTERM		BRADENHEAD	INTERMEDIATE
TIME		Int	Csg	Int	Csg		
5 min		190	99		99	Steady Flow	X
10 min		190	99		99	Surges	
15 min		190	99		99	Down to Nothing	
20 min					99	Nothing	X
25 min					99	Gas	X
30 min					99	Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1.4

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME
OUT. OPENED THE INTERMEDIATE AND IT FLOWED FOR
THE ENTIRE 30 MINUTES OF THE TEST.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____