



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://omnr.d.state.nm.us/ocd/District/1033distric.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT  
(submit 1 copy to above address)

MAY 01 2013

Date of Test 4-19-13 Operator Chevron midcon API # 30-039-24662

Property Name Rincon Well No. 252 Location: Unit 6 Section 18 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 25 Intermediate X Casing 25 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	1	25		
10 min	0		25		
15 min	0		25		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Randy Culcote  
Culcote  
(Position)

Witness \_\_\_\_\_

E-mail address Randy.c@wildersave.com

4-22-13