



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omnr.state.nm.us/ocd/District/112/district.htm>

OIL CONS. DIV DIST. 3

MAY 01 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-23-13 Operator B Heaton midwest API #30-039-27803

Property Name Rincon Well No. 412 Location: Unit 7 Section 26 Township 22 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 31 Intermediate X Casing 61 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		60		
10 min	0		60		
15 min	0		54		
20 min					
25 min					
30 min					

well
went
online
13 min

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing X P.O.F.F.

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

TBg went online at 13 min causing csg drop, bradenhead
dead

By Randy calcoTE
calder service
(Position)

Witness _____

E-mail address Randy.c@calder-service.com

4-24-13