



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 23 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-18-13 Operator Chevron Midcon API #30-0 39-21720

Property Name Rincon Well No 91A Location: Unit P Section 18 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 34 Intermediate X Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		38		
10 min	0		38		
15 min	0		39		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X PUFF	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE X

REMARKS:

Bradenhead Had PUFF when opened, Then dead.

By Randy Culcote

Witness _____

Culder Service
(Position)

E-mail address Randy.C@calderservice.com

4-22-13