



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
APR 18 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-13 Operator WPX Energy API #30-0 3927464

Property Name Rosa Unit Well No. 337A Location: Unit D Section 32 Township 31N Range 05W

Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate N/A Casing 52 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>52</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>52</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>52</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead was at 0 psi. Left valve open

By Carlos Flores

Witness _____

Tech II

(Position)

E-mail address Carlos.Flores@wpxenergy.com