



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III/3distric.htm](http://emrmd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

APR 23 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-17-13 Operator Chevron midcont API # 30-039-60093

Property Name Rincon Well No 107 Location: Unit K Section 19 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate X Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		32		
10 min	0		32		
15 min	0		31		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X Puff	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.c@culderservice.com

4-18-13