



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 24 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/16/2013 Operator WPX Energy API #30-0 3921758

Property Name Rosa Unit Well No. 066 Location: Unit L Section 13 Township 31N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 84 Intermediate Ø Casing 118 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

After 24 hour shut both the BH and INT valves had no pressure or fluid, after testing left BH and INT valves open.

By Stacey McLendon

Witness _____

Field Tech

(Position)

E-mail address stacey.mclendon@yahoo.com