



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

MAY 07 2013

Date of Test 4-16-2013 Operator WPX Energy API #30-0 3906897

Property Name JICARILLA 92 Well No. 002 Location: Unit K Section 29 Township 27N Range 03W

Well Status (Shut-In or Producing) Initial PSI: Tubing 227 Intermediate N/A Casing 277 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	N/A	277		
10 min	0	N/A	277		
15 min	0	N/A	277		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>0</u> psi	N/A
Nothing <u>0</u> psi	N/A
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Opened BH showed 0 psi, small amount of psi escaped down to nothing left valve open after test.

By Curt Heckman

Witness _____

Tech III
(Position)

E-mail address curt.heckman@wpxenergy.com