



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 13 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-25-13 Operator Elm Ridge Exploration CO LLC API #30-039-20181

Property Name Cinco Diablos Well No. 012 Location: Unit I Section 14 Township 23N Range 04W

Well Status(Shut-In or Producing) Initial PSI: Tubing 63 Intermediate N/A Casing 78 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		78		
10 min	1		1		
15 min	1		1		
20 min	1		1		
25 min	1		1		
30 min	0		78		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By WESLEY RAY

Witness \_\_\_\_\_

PUMPER

(Position)

E-mail address \_\_\_\_\_