



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

AUG 06 2013

Date of Test 7-29-13 Operator CROSS TIMBERS ENERGY SAPI #30-0 39-23234

Property Name Breach D Well No. 341M Location: Unit F Section 21 Township 26N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 109 Intermediate N/A Casing 119 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>119</u>			Steady Flow	
10 min	<u>0</u>		<u>119</u>			Surges	
15 min	<u>0</u>		<u>119</u>			Down to Nothing	
20 min						Nothing	<u>✓</u>
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

By [Signature]

Witness _____

(Position)

E-mail address _____