



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 06 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

CROSS TIMBERS

Date of Test 7-23-13 Operator ENERGY API #30-0 39-60060

Property Name Breech A Well No. 133 Location: Unit D Section 10 Township 26N Range 6W

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 90 Intermediate NA Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>90</u>		
10 min	<u>0</u>		<u>90</u>		
15 min	<u>0</u>		<u>90</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: BRADENHEAD Less Than 1 LB, DOWN TO NOTHING IN 30 SEC.

By Kevin Johnson

Witness _____

(Position)

E-mail address _____