



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emrdr.state.nm.us/ocd/District III/3distric.htm>

OIL CONS. DIV DIST. 3

AUG 06 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

CROSS TIMBERS

Date of Test 7-29-13 Operator ENERGY API #30-0 39-82262

Property Name Breach D Well No. 341 Location: Unit B Section 21 Township 26N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 140 Intermediate NA Casing 141 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		141		
10 min	0		141		
15 min	0		141		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]

Witness \_\_\_\_\_

(Position)

E-mail address \_\_\_\_\_