



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 15 2013

Date of Test 8/7/2013 Operator Western Minerals and Oil API #30-0 45-13244

Property Name Marron Well No. 4 Location: Unit Section 27 Township 27N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 7 Intermediate Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>				<u>7</u>
10 min	<u>0</u>				<u>7</u>
15 min	<u>0</u>				<u>7</u>
20 min	<u>0</u>				<u>7</u>
25 min	<u>0</u>				<u>7</u>
30 min	<u>0</u>				<u>7</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Hbd zero pressure and did not build up any pressure. No liquids

By Bali Chenault
Lease Operator
(Position)

Witness

E-mail address bob@ccinm.com