



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

AUG 15 2013

(submit 1 copy to above address)

Date of Test 8/7/2013 Operator Western Minerals and Oil API #30-0 45-21323
Property Name Marron Well No. 6 Location: Unit Section 24 Township 27N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate - Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0				35
10 min	0				35
15 min	0				35
20 min	0				35
25 min	0				34
30 min	0				35

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Had zero pressure and did not build up any pressure. No liquids

By Bob Chenault
Lease Operator
(Position)

Witness

E-mail address bob@ccnm.com