



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1800 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6179
<http://emrmd.state.nm.us/ocd/District%20103/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 01 2013

Date of Test 4-24-13 Operator Chewer mid cut API #30-039-06925

Property Name Rincon Well No. 70 Location: Unit A Section 27 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 29 Intermediate X Casing 61 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		61		
10 min	0		61		
15 min	0		60		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy calcoTE
calder service
(Position)

Witness _____

E-mail address Randy.calcoTE@calder service.com