



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 05 2013

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 7-31-13 Operator Elm Ridge Exploration CO LLC API #30-039-26885

Property Name Otero Well No. 001 Location: Unit B Section 5 Township 23N Range 05W

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH



FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
<u>Down to Nothing</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

BRADENHEAD had less than 1" on it Blew down in
A couple of seconds. Pumping unit on well
producing casing

By Don L. Voss

Witness _____

(Lease Operator (pumper))
(Position)

E-mail address _____