



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 05 2013

Date of Test 7-23-13 Operator Elm Ridge Exploration CO LLC API #30-039-29284

Property Name Jicarilla Apache B Well No. 024 Location: Unit A Section 30 Township 24N Range 05W

Well Status(Shut-In or Producing) Initial PSI: Tubing 18 Intermediate N/A Casing 27 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>27</u>		
10 min	<u>0</u>		<u>27</u>		
15 min	<u>0</u>		<u>27</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
<u>Nothing</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Bradenhead had a very slight vacuum on it

By Don L. Voss

Witness _____

lease operator (pumper)
(Position)

E-mail address _____