



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-8170  
www.emnrd.state.nm.us/ocd/District%203/district3.htm

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

OIL CONS. DIV DIST. 3

SEP 19 2013

Date of Test SEPT 12, 2013 Operator PARKO INC. API #30-0-43-20687  
Property Name Lulu Well No. 4 Location: Unit 1 Section 29 Township 23N Range 6W  
Well Status (Shut-In or Producing) Tubing 50 Intermediate \_\_\_\_\_ Casing 210 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes				Steady Flow	
10 minutes				Surges	
15 minutes				Down to Nothing	
20 minutes				Nothing	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS: Pumping Unit Shut In 24 hrs

By Johnny Arroyo Witness \_\_\_\_\_  
Pumper  
(Position)

E-mail address Dr 290N Johnny@yahoo.com