



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-12-13 Operator Elm Ridge Exploration CO LLC API #30-039-08111

Property Name: Skelly Florance Well No. 002 Location: Unit G Section 5 Township 23N Range 04W

Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate N/A Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	N/A	60		
10 min	0	N/A	60		
15 min	0	N/A	60		
20 min	0	N/A	60		
25 min	0	N/A	60		
30 min	0	N/A	60		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

JUL 08 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

0 ON Braden Head

By Epi M

Witness _____

R - Pumper
(Position)

E-mail address _____