

& NATURAL RESOURCÉS DEPARTMENT

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

OIL CONS. DIV DIST. 3

JUL 1 5 2013

Date of Test $6-12-13$	Operator	NM&O Operating Co.	_API #30-0 <u>39239</u> :	1300D2
Property Name Bearcat Well No. 1 Location: Unit O Section 22 Township 25N Range 2W				
Well Status(Shut-In or Producing) Tubing 25 Intermediate /// Casing 25 Bradenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
TIME ENTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O	25	Steady Flow		
10 minutes O	25	Surges	·	
15 minutes	25	Down to Nothing	3	
20 minutes		Nothing X	ا مهي	
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE With.				
REMARKS:				
By Cambris Witness Witness				
(Position)				