



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emhnd.state.nm.us/ocd/District%20District.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

JUN 19 2013

Date of Test 6-12-13 Operator Chuvon API # 30-039-06891

Property Name Rincon Well No. 34 Location: Unit K Section 28 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 92 Intermediate X Casing 93 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		93		
10 min	0		93		
15 min	0		93		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing <u>X</u>		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS:

By Randy CalcoTE
Calder Service
(Position)

Witness _____

E-mail address Randy.C@calder service.com

6-18-13